

Longhill Station Homeowners

Neighbors,

Early this morning, (4/27 at 7:15 AM) a neighbor reported water flowing in the gutter at the Pool Club House. (See Photo)

BoD members arrived quickly to assess the immediate situation, and to initiate an emergency call to Continental Pool for assistance.



Assessed as a supply line leak up to but not inside the clubhouse. (This is not a Pool or Filtration System issue, and so turning off the main water supply from the main Inlet (curbside supply) stopped the leak.) This step turned off the water to the entire Clubhouse.

The BoD is taking the necessary steps to identify the location and hopes to schedule a repair of the leak in the coming week.

Updates to follow when available.

V/R
LHS HOA BoD